

ENERGY SAVINGS IN BROOKLYN

NY Building Systems Consultant Inc. (NYBSC) finished the comprehensive energy study as well as NYC Local Law 87 Compliance services for the building; has 12 floors, located in New York.

BUILDING PROFILE

Address: 125 North 10th Street, Brooklyn, NY-11249
Square Foot: 225,356
Type: Multi-Family Elevator Buildings
Units: 93
Year of Built: 2007



NYBSC SERVICES

- Energy Audit
- Retro-Commissioning (RCx) analysis
- Cogeneration feasibility Study
- NYC Local Law 87 (LL87)

PROJECT SUMMARY

ANNUAL COST SAVINGS: \$30,464 | IDENTIFYING TOTAL 13 ITEMS ENERGY CONSERVING MEASURES INCLUDING

- ✓ Lighting Upgrades
- ✓ Motor Replacement
- ✓ Installation of VFDs on Motors
- ✓ Separate Solar DHW Heater Installation
- ✓ Replacing the dirty air filters
- ✓ Conventional Boilers to Condensing Boilers Replacement

