

HUGE ANNUAL COST SAVINGS IN 90 WILLIAM STREET

NY Building Systems Consultant Inc. (NYBSC) fruitfully performed comprehensive energy study as well as NYC Local Law 87 Compliance services for 90 William Street; constructed in 1967; has 17 floors; Mixed commercial and residential building located in New York.

BUILDING PROFILE

Address: 90 William Street, NY -10038
 Square Foot: 126,291
 Type: Mixed Residential and Commercial
 Units: 116
 Year of Built: 1967



NYBSC SERVICES

- Energy Audit ASHRAE Level 2
- Retro-Commissioning (RCx) analysis
- Cogeneration feasibility Study
- NYC Local Law 87 (LL87)

PROJECT SUMMARY

ANNUAL COST SAVINGS: \$144,851 | IDENTIFYING TOTAL 22 ITEMS ENERGY CONSERVING MEASURES.

✓ Steam to Boilers Replacement	✓ Cogenerations Installation	✓ VFD Installation
✓ RTU Replacement	✓ Lighting Upgrade	
✓ Clean and fix the broken coil of the RTU		

